MATERIAL SAFETY DATA SHEET

May be used to comply with

OSHA's Hazard Communications Standard,

29 CFR 1910. Standard must be consulted for specific requirements.

U.S. Department of Labor

Occupational Safety and Health Administration

(Non-Mandatory Form)

Form Approved OMB N. 1218-0072

IDENTITY:	NOTE: Blank spaces are not permitted. If any item is not applicable,
SLICK RED SPRAY GREASE	or no information is available, the space must be marked to indicate
A885	that.

11003							
HMIS RATING:	HEALTH:	1	FLAMMABILI	TY: 1	REACTIV	ITY: 0	
RATING LEGEND:	4 = extreme,	3 = serious,	2 = moderate,	1 = slight,	0 = minimal,	* = chronic hazard	d

Section I

Distributed	Handi-Clean Products, Inc. 301 Swing Rd.	Emergency Telephone Num (336) 292-3083 After 5:00 p.m. (33	
By:	Greensboro, NC 27409	Telephone Number for Information	_
	(336) 292-3083	1/7/2010	

Section II - Hazardous Ingredients/Identity Information

Hazardous Components				Other Limits	
(Specific Chemical Identity; Common Name(s))	CAS NO.	OSHA PEL	ACGIH TLV	Recommended	% (optional)
Paraffin Oil	8012-95-1		5 mg/m ³ as mist		
Propane	74-98-6		2500ppm		
Hexane	110-54-3		50ppm		
Isohexane Isomers	107-83-5		500ppm		
Butane	106-97-8		800ppm		
Tetrachloroethylene	127-18-4		25ppm		
Antimony Metal Salt	Unknown		0.5 mg/m^3		

Section III - Physical/Chemical Characteristics

Boiling Point:	<0 to 601°F Specific Gravity	$V(\mathbf{H}_20=1)$:	0.75 ± 0.05	Appearance:	Red Liquid
Vapor Pressure (mmHg):		Evaporatio	n Rate:	Odor:	Aerosol
Vapor Density (AIR = 1):	Heavier than air	Slower than	Ether	Solubility in Water:	Nil

Section IV - Fire and Explosion Hazard Data

Flash Point (Method Used): >200°F	Flammable Lim	its LEL: 1.0	UEL: 9.5			
Extinguishing Media: Use water fog, dry chemical or carbon dioxide. Flash Point (Propellant): <0°F						
Special Fire Fighting Procedures: Aerosol cans may rupture when heated.						
Unusual Fire and Explosion Hazards: Heated cans may burst.						

Section V - Reactivity Data

Stability:	Stable	X		Unstable				
Hazardous Polymerizati	on:	May Occur			Will Not	Occur	Σ	K
Incompatibility (Materia	als to Avoid):	None known.						
Hazardous Decompositi	ion or Bypro	ducts: In fire	, will decon	npose to car	bon dioxide,	carbon	monoxide,	hydrogen
chloride, oxides of metal i	in section 2.							
Conditions to Avoid: Hi	igh temperatur	es.						

(Reproduced locally) OSHA 174, Sept. 1985

Section VI - Health Hazard Data

Route(s) of Entry: Inhalation? X Skin? X Eyes? X Ingestion? X

Health Hazards (Acute and Chronic): Effects of Overexposure: SKIN: Skin irritant. Will cause defatting of skin. Effects are reversible. EYES: Eye irritant. Will cause redness and burning sensation. INHALATION: Effects of overexposure include irritation of respiratory tract, headache, dizziness, nausea, and loss of coordination. Extreme

Medical Conditions Generally Aggravated by Exposure: Prolonged and repeated overexposure to hexane may cause damage to nerve tissue of the arms and legs (peripheral neuropathy), resulting in muscular weakness and loss of sensation. Repeated and prolonged overexposure to solvents can cause permanent brain and nervous system damage.

overexposure may result in unconsciousness and possibly death. INGESTION: Aspiration hazard if swallowed.

Emergency and First Aid Procedures: SKIN: Immediately flush exposed area with water for at least 15 minutes. If irritation persists, get medical attention. Remove contaminated clothing and launder before reuse. EYES: Immediately flush with large quantities of water for at least 15 minutes, lifting upper and lower eyelids occasionally. Remove contact lenses, if present. Seek medical attention. INHALATION: Remove person to fresh air. If irritation persists, give oxygen, get medical attention. INGESTION: DO NOT induce vomiting. Seek medical attention immediately. NOTE: Never give anything by mouth to an unconscious or convulsing victim. Keep person warm and quiet.

Section VII - Precautions for Safe Handling and Use

Steps to Be Taken in Case Material is Released or Spilled: Use absorbent sweeping compound to soak up material. Put into container. Dispose as hazardous waste.

Waste Disposal Method: Dispose as hazardous waste in accordance with EPA RCRA, Local, State and Federal Regulations.

Precautions to Be Taken in Handling and Storing: When spraying more than one half can continuously or more than one can consecutively, use NIOSH approved respirator. Store at temperatures below 120°F. Keep away from heat, sparks, or open flame. For industrial and institutional use only. Keep container closed during storage. For use by trained personnel only.

Other Precautions: KEEP OUT OF REACH OF CHILDREN.

Section VIII - Control Measures

Respiratory Protection (Specify Type): Self-contained breathing	Ventilation: Provide local exhaust to keep TLV of				
apparatus if above TLV limit.	Section 2 ingredients below acceptable limit.				
Protective Gloves: None required if spraying.	Eye Protection: We recommend the use of safety				
Other Protective Clothing or Equipment: Long sleeves and long	glasses or chemical splash goggles.				
pants.					
Work/Hygienic Practices: Wash hands with soap and water after using product. Do not smoke while using.					

(Reproduced locally) OSHA 174, Sept. 1985